



Office of the District Fire Officer  
North Fire Station,  
Karnataka Fire & Emergency Services  
B.M Road, Bengaluru..



No. 44/DFO/NFS/Bng/FSR/2022

Dated: 13-09-2022.

"Annexure-2"

To,  
The Manager,  
Bharathiya Vidhya Bhavan's,  
Bruhath Bengaluru Mahanagara  
Palike Public School,  
No-21, ward No 97, 5<sup>th</sup> main Road,  
Kranthi Kavi Sarvagnya Road,  
Srirampura, Bengaluru-560021.

Sir,

**Sub :** Issue of "Fire Safety Compliance report" with respect to fire prevention, fire fighting and evacuation measures maintained at "**Bharathiya Vidhya Bhavan's, Bruhath Bengaluru Mahanagara Palike Public School, No-21, ward No 97, 5<sup>th</sup> main Road, Kranthi Kavi Sarvagnya Road, Srirampura, Bengaluru-560021.**" - reg.

**Ref :** 1) This office FSR No.44 /DFO/NFS/Bng/FSR/2022 Date: 13-09-2022.  
2) Your request letter dated: 01-09-2022.

<<<>>>

With reference to the above cited subject, as per ref(1), a conditional Fire Safety Recommendation was issued to the premises of "**Bharathiya Vidhya Bhavan's, Bruhath Bengaluru Mahanagara Palike Public School, No-21, ward No 97, 5<sup>th</sup> main Road, Kranthi Kavi Sarvagnya Road, Srirampura, Bengaluru-560021**" with a condition to fulfill the recommendations and compliance the same within 3 months.

With reference cited (2) above, the management of "M/s. **Bharathiya Vidhya Bhavan's**" had requested for the fire safety compliance report from our department. In this regard the District fire officer, North Fire Station, Bengaluru was inspected on 06-09-2022 and submitted the report to issue fire safety Compliance report.

Under the above circumstance the Karnataka Fire & Emergency Services Department is issuing the "Fire Safety Compliance Report" to "**M/s Bharathiya Vidhya Bhavan's, Bruhath Bengaluru Mahanagara Palike Public School, No-21, ward No 97, 5<sup>th</sup> main Road, Kranthi Kavi Sarvagnya Road, Srirampura, Bengaluru-560021**" subject to proper maintenance of fire fighting installations in the good working conditions, one generator of Suitable capacity to supply alternative power for staircase lighting, corridor lighting etc., in the event of failure of electricity supply in the building and arrange for 40% of staffs/ employees training within 03 months from the date of issue of this report. "This report is valid up to only one year from the date of issue and is renewable without fail".



Yours faithfully,  
District Fire Officer  
Karnataka State Fire & Emergency Services  
North Fire Station, Mysore Road,  
Bangalore - 560 018